## POM-H

## POLYACETAL HOMOPOLYMER

## **Material description**

POM-H is a highly crystalline thermoplastic which has a higher creep resistance, tensile strength, hardness, stiffness and abrasion resistance than POM-C. However, POM-H is less resistant to hydrolysis and has lower chemical resistance. POM-H should not be used in environments with hot steam or boiling water.

## **Conformities**

RoHS, REACH

Physical properties	Test method	Value	Unit
Density	DIN EN ISO 1183-1	1.43	g/cm3
Water absorbtion	DIN EN ISO 62	0.21	%
Sliding friction		•	
Abrasion resistance		•	

Mechanical properties	Test method	Value	Unit
Yield stress	DIN EN ISO 527	78	MPa
Elongation at break	DIN EN ISO 527	25	%
Tensile modulus of elasticity	DIN EN ISO 527	3700	MPa
Notched impact strength	DIN EN ISO 527	10	kJ/m2
Ball indentation hardness	DIN EN ISO 2039-1	160	MPa

Thermal properties	Test method	Value	Unit
Thermal conductivity	DIN 52612-2	0.31	W/(m*K)
Heat capacity	DIN 52612-1	1.5	kJ/(kg*K)
Coefficient of thermal expansion	DIN 53752	95	10 <sup>-6*K</sup> -1
Operating temperature short term		150	°C
Operating temperature long term		-50 bis 90	°C
Heat deflection temperature	DIN EN ISO 75 / A	110	°C
Flammability	UL 94, 3 mm	HB	

Electrical properties	Test method	Value	Unit
Volume resistivity	IEC 60093	10 <sup>15</sup>	$\Omega$ * cm
Surface resistivity	IEC 60093	10 <sup>15</sup>	Ω * cm
Dielectric strength	IEC 60243	20	kV/mm
Comparative tracking index (CTI)	IEC 60112	600	CTI

These technical data have been determined as average values by our suppliers from many individual measurements. In all measurements, the test specimens were tested in the dry state. We pass on the data with reservation. The table does not claim to be complete or correct. Material technology is subject to constant further development. No rights or guarantees can be derived from it. Own tests are necessary because the environmental and operating conditions (humidity, temperature, mechanical forces, radiation and chemicals, etc.) set limits in the application.

